

# IMPORTANT SAFETY NOTICE

## ADP Separated Combustion Gas-Fired Unit Heaters

Some heaters identified below were mistakenly manufactured without a required “flame rollout switch,” which is a backup device designed to shut down the heater and prevent a fire in the event of certain types of heater failures. No reports of incident or injury have been received.

Heating Capacity	Model Number	Serial Number Range	Dates of Possible Sale
60,000 BTUH	FOAN-60-1-1-1	5609K##### to 5610M#####	Oct. 2009-Apr. 2011
100,000 BTUH	FOAN-100-1-1-1	6003J##### to 6010L##### 5603J##### to 5610L#####	Sept. 2003-Apr. 2011
100,000 BTUH	FOAP-100-1-1-1	6003J##### to 6010L##### 5603J##### to 5610L#####	Sept. 2003-Apr. 2011
125,000 BTUH	FOAN-125-1-1-1	6003J##### to 6010L##### 5603J##### to 5610L#####	Sept. 2003-Apr. 2011
125,000 BTUH	FOAP-125-1-1-1	6003J##### to 6010L##### 5603J##### to 5610L#####	Sept. 2003-Apr. 2011



**Affected heaters will be inspected and repaired, if necessary, free of charge.**

For information, call ADP toll-free at (866) 303-8634 between 8 a.m. and 4 p.m. CT Monday through Friday, or visit [www.adpnow.com](http://www.adpnow.com).